

### 职业卫生检测报告公示

用人单位名称	武义隆迪紧固件有限公司
地址	武义县东南工业区（武义县恒力弹簧厂内）
联系人	陈芬
项目组成人员	刘文博、徐华超
现场调查人员	章豪峥
现场调查时间	2023. 10. 08
现场采样/检测人员	刘文博、徐华超
现场采样/检测时间	2023. 10. 08
用人单位陪同人员	张勇军
现场图像	 The first photograph shows the exterior of the factory building, which is partially covered by a green tarp. A red truck is parked in front of the entrance. The second photograph shows the interior of the factory, where two workers are operating machinery. One worker is bent over a large metal tray, and the other is standing nearby, possibly inspecting or operating the equipment. The factory floor is cluttered with various tools and materials.